

12/16/15

MY 15, 16

All Bodies

## GPOP - Issue Review System

**Part Number:** 53034160A\$, 68044317A\$, 04861714A\$, 04861727A\$, 68043161A\$, 05281418A\$, 05281225A\$, 53032868A\$, 68208213A\$, 52124785A\$, 04581697A\$, 04581652A\$, 04891585A\$

**Part Description:** Accelerator Pedal

---

**Issue Description:** Vehicle has accelerator pedal fault code. Before replacing accelerator pedal, be sure to follow fault code diagnostic procedures in service manual. Make sure to check wiring and connectors. DTC P2299 is usually caused by a two footed driver and accelerator pedal should not be replaced for this fault.

~  
Contact Us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.

---